

James A. FitzPatrick
Nuclear Power Plant
P.O. Box 41
Lycoming, New York 13091
315 342-3840



Harry P. Salmon, Jr.
Resident Manager

December 6, 1993
JAAP-93-0653

United States Nuclear Regulatory Commission
Document Control Desk
Mail Station P1-137
Washington, D.C. 20555

SUBJECT: DOCKET NO. 50-333
LICENSEE EVENT REPORT: 93-009-01 - Low Reactor Water
Level Scram Due to Feedwater
Transient

Dear Sir:

This report was submitted in accordance with 10 CFR 50.73
(a)(2)(iv), 10CFR50.73(a)(2)(v)(D) and 10CFR50.73(a)(2)(i)(B).

This supplement corrects an editorial error identifying the valve
number of the second containment isolation valve on Page 7.

Questions concerning this report may be addressed to
Mr. Donald Simpson (315) 349-6361.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'Harry P. Salmon, Jr.'.

HARRY P. SALMON, JR.

HPS:DFS:tlc
Enclosure

cc: USNRC, Region 1
USNRC Resident Inspector
INPO Records Center

140056
9312150050 931206
PDR ADOCK 05000333
S PDR

IE22
11