

# LICENSEE EVENT REPORT

CONTROL BLOCK 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 M N M N P 1 1 0 0 - 0 0 0 0 - 0 0 4 1 1 1 1 0 1

CATEGORY 01 CONT P 0 T L 0 5 0 - 0 2 6 3 0 9 3 0 7 5 1 1 1 1 7 5

## EVENT DESCRIPTION

02 While performing local leak rate test, CRD outboard isolation valve CRD-31 was  
03 found leaking in excess of the acceptance criteria. One similar previous event.  
04 Cleaned valve seats. (AO 263/75-17-6)  
05  
06

SYSTEM CODE 07 S D E V A L V E N A 3 9 5 Y

## CAUSE DESCRIPTION

08 Failed leak test due to accumulation of scale on seating surface. 3-inch, 900-lb.  
09 swing check valve. Vendor drawing number 2257-5, Anchor Valve Company. Cleaned  
10 and lapped valve seats, retested satisfactory.

FACILITY STATUS 11 H 0 0 0 N B N

FORM OF ACTIVITY RELEASED 12 Z 2 N N N

## PERSONNEL EXPOSURES

13 0 0 0 Z N

## PERSONNEL INJURIES

14 0 0 0 N

## OFFSITE CONSEQUENCES

15 N

## LOSS OR DAMAGE TO FACILITY

16 Z N

## PUBLICITY

17 N

## ADDITIONAL FACTORS

18 N

19 N

NAME J. D. McVay

PHONE 612/295-5151

9105070388 751111  
 CF ADDOCK 05000263  
 CF