



Nebraska Public Power District

COOPER NUCLEAR STATION
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321
TELEPHONE (402) 825-3811

CNSS937262
October 18, 1993

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Subject: Section XI Code Reports
Cooper Nuclear Station
NRC Docket No. 50-298, DPR-46

Reference: ASME Section XI, 1980 Edition, Winter 1981 Addenda,
Article IWA-6000


Gentlemen:

Pursuant to the reporting requirements of the above reference, the subject code reports are submitted as enclosures to this letter for review by your office.

Enclosure 1, "Owner's Data Report for Inservice Inspections" (Form NIS-1), documents Inservice Inspection activities conducted at Cooper Nuclear Station during refueling outage number 15 (Spring 1993 Refueling Outage). Enclosure 2, "Owner's Report for Repairs and Replacements" (Form NIS-2), documents repair and replacement activities conducted during operating cycle number 15 and refueling outage number 15.

If you should require additional information regarding this information, please call.

Sincerely,



G. R. Horn
Vice President-Nuclear

GRH:sa

Enclosures

cc: Regional Administrator
NRC Region IV
Arlington, Texas

250143

NRC Resident Inspector
Cooper Nuclear Station

9310270104 931018
PDR ADOCK 05000298
Q PDR

1047