



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

December 22, 1982

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

DEC 27 10:32

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Drywell to Containment
Differential Pressure Not
Verified at the Proper
Frequency
LER 82-146/03 L-0
AECM-82/632

An internal Quality Assurance audit has revealed the drywell to containment differential pressure was not verified between -0.1 and ± 2.0 psid at the proper frequency required by Technical Specification 3.6.2.5 while in Hot Shutdown. This event is being reported pursuant to Technical Specification 6.9.1.13.c. Attached is LER 82-146/03 L-0.

Yours truly,

JPM:sap
Attachment

cc: Mr. N. L. Stampley (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

LE 12