

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

DEC 27 11:44

December 22, 1982


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-80. This report concerns T.S. 4.3.1.1., "Each Reactor Trip System instrumentation channel and interlock shall be demonstrated operable by the performance of the channel check, channel calibration and channel functional test operations for the modes and at the frequencies shown in Table 4.3-1". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

PBN:jfw
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Senior Resident Inspector
McGuire Nuclear Station

8212300093 821222
PDR ADOCK 05000369
S PDR

OFFICIAL COPY

IE 22