

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

December 23, 1982

HAL B. TUCKER

VICE PRESIDENT

NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

✓ Mr. J. P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Oconee Nuclear Station
Docket No. 50-287

Dear Mr. O'Reilly:

On December 13, 1982 your office was informed that two manual containment isolation valves were discovered open. This concerns an operation subject to a limiting condition for operation which was less conservative than the least conservative aspect of the limiting condition for operation established in the Technical Specifications. Reportable Occurrence Report RO-287/82-15 providing details of this incident was to have been submitted to you by December 24, 1982, pursuant to Technical Specification 6.6.2.1.a(2). However, the investigation of this incident and the preparation of a report are incomplete at this time. It is expected that the investigation and report will be completed, reviewed, and submitted to you no later than December 31, 1982.

Very truly yours,

H. B. Tucker / BT

Hal B. Tucker

JCP:scs

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Philip C. Wagner
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
Oconee Nuclear Station

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

8212300224 821223
PDR ADOCK 05000287
S PDR

OFFICIAL COPY

IE 22