

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

December 23, 1982

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-259/82099

The enclosed report provides details concerning a leak found in a  
cracked 1/2-inch core spray system sample connection pipe. This  
report is submitted in accordance with Browns Ferry unit 1 Technical  
Specification 6.7.2.a(3).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Green*  
H. J. Green

Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

RECEIVED  
REGION II  
DEC 28 11:43

8301030047 211223  
PDR ADOCK 05000259  
S 8 PDR

An Equal Opportunity Employer

OFFICIAL COPY  
TE 22