

## LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C A S 0 5 2 0 0 - 0 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 0 5 0 0 0 3 6 1 7 1 1 2 8 8 2 8 1 2 1 3 8 2 9

60 61 DOCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 With the plant in Mode 3 Emergency Chiller E-335 was declared inoperable. This

0 3 rendered CREACUS Train B inoperable. Since Train A was down for charcoal filter

0 4 replacement, LCO 3.7.5 was thus exceeded and LCO 3.0.3 became governing for both

0 5 units. No event requiring CREACUS operation during this period occurred, thus

0 6 public health and safety were not affected.

0 7

0 8

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

S G 11 D 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16

9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 8 2 1 4 2 0 1 0 1 0

21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRPD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

G 18 X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 9 26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 This event was caused by the failure of a Resistance Temperature Detector (RTD)

1 1 in the motor winding high temperature trip circuit. Corrective measures taken included

1 2 a temporary modification and clearing of the trip. Also; an installed spare RTD

1 3 will be used in the trip circuit as permanent corrective action.

1 4

FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32

1 5 B 28 0 0 0 29 NA A 31 Operator Observation

7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1 6 Z 33 Z 34 NA

7 8 9 10 11 44 45 46 80

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39

1 7 0 0 0 37 Z 38 NA

7 8 9 10 11 12 13 44 45 46 80

PERSONNEL INJURIES NUMBER DESCRIPTION 41

1 8 0 0 0 40 NA

7 8 9 10 11 12 13 44 45 46 80

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43

1 9 Z 42 NV

7 8 9 10 11 12 13 44 45 46 80

PUBLICITY ISSUED DESCRIPTION 45

2 0 N 44 NA

7 8 9 10 11 12 13 44 45 46 80

NRC USE ONLY

NAME OF PREPARER H. B. Ray HB Ray / TVM

PHONE 714/492-7700