

PROMPT REPORTABLE OCCURRENCE

AS OF

Certified By

m d p

TELECOPY MESSAGE

TO: (215) 337-5324
Telephone Number

DATE/TIME: 12/13/82 / 1330

TO: Ronald C. Haynes
Regional Administrator, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406FROM: Pilgrim Nuclear Power Station
RFD#1, Rocky Hill Road
Plymouth, MA 02360Docket Number 50-293
License DPR-35

Assigned LER Number 82-056/01X-0

Reported per T.S. Section 6.9.B.1.i

Event Description: On 12/13/82, PNPS received an evaluation that found that a fire barrier (blow out panel), that had been 3 hour rated by the A/E in 1974, is actually a 2 hour rated barrier thereby rendering the panel non-functional per T.S. Section 3.12.F.

Cause and Corrective Action: A continuous fire patrol was established per T.S. action statement. An engineering evaluation is continuing to determine the most effective corrective action to be taken considering all parameters.

Facility Status: 0 % Thermal MW

c) Routine Startup
d) Routine Shutdown X
e) Steady State
f) Load Changing

g) Shutdown
h) Refueling
i) Other
j) Not Applicable

A written followup report will be sent within two weeks.

NRC Person Notified J. R. Johnson USNRC Prepared by G. G. Whitney
Resident Inspectorcc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECo. LER Distribution