

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6
---	---	---	---	---	---

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

 N J S G S 1 

2	0	0	-	0	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---	---	---

3	4	1	1	1	1
---	---	---	---	---	---

4	5
---	---

  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0	1
---	---

 REPORT SOURCE L 

6	0	5	0	0	0	2	7	2
---	---	---	---	---	---	---	---	---

7	0	1	1	9	8	2
---	---	---	---	---	---	---

8	1	2	2	9	8	2
---	---	---	---	---	---	---

9
---

  
7 8 60 61 68 69 74 75 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2
---	---

 On January 19, 1982, while performing surveillance requirements to demonstrate  

0	3
---	---

 steam generator operability, indications of tube thinning was detected by eddy  

0	4
---	---

 current examination. No. 12 Steam Generator required two sample inspections.  

0	5
---	---

 No. 14 Steam Generator required three sample inspections, and reporting as required  

0	6
---	---

 by C-3 result in Technical Specification Table 4.4-2.  

0	7
---	---

  

0	8
---	---

  
7 8 9 80

0	9
---	---

 SYSTEM CODE C C (11) CAUSE CODE E (12) CAUSE SUBCODE C (13) COMPONENT CODE H T E X C H (14) COMP. SUBCODE F (15) VALVE SUBCODE Z (16)  
7 8 9 11 12 13 18 19 20  

17
----

 LER NO. REPORT NUMBER 8 2 (17) EVENT YEAR 8 2 (18) SEQUENTIAL REPORT NO. 0 0 2 (19) OCCURRENCE CODE 0 1 (20) REPORT TYPE X (21) REVISION NO. 2 (22)  
21 22 23 24 26 27 28 29 30 31 32  
ACTION TAKEN F (18) X (19) FUTURE ACTION Z (20) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 (22) ATTACHMENT SUBMITTED Y (23) NPD-4 FORM SUB. Y (24) PRIME COMP. SUPPLIER N (25) COMPONENT MANUFACTURER W 1 2 0 (26)  
33 34 35 36 37 40 41 42 43 44 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0
---	---

 All tubes degraded above 30% were plugged. Additional exams of Nos. 11 and 13 SG's  

1	1
---	---

 were conducted and all tubes degraded above 30% were plugged. Tube R44C62 was sent  

1	2
---	---

 to Westinghouse Research and Development Center for chemical and metallurgical testing  

1	3
---	---

  

1	4
---	---

  
7 8 9 80

1	5
---	---

 FACILITY STATUS H (28) % POWER 0 0 0 (29) OTHER STATUS N/A (30) METHOD OF DISCOVERY C (31) Eddy Current Examination (32)  
7 8 9 10 12 13 44 45 46 80  

1	6
---	---

 ACTIVITY CONTENT RELEASED OF RELEASE Z (33) Z (34) AMOUNT OF ACTIVITY N/A (35) LOCATION OF RELEASE N/A (36)  
7 8 9 10 11 44 45 80

1	7
---	---

 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION N/A (39)  
7 8 9 11 12 13 80

1	8
---	---

 PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION N/A (41)  
7 8 9 11 12 80

1	9
---	---

 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION N/A (43)  
7 8 9 10 80

2	0
---	---

 PUBLICITY ISSUED N (44) DESCRIPTION N/A (45)  
7 8 9 10 80

NAME OF PREPARER R. Heller

PHONE: (609) 935-6000 Ext 3078