

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency Report No. 62
"Undersize Welds on 1/2" Schedule 160 Pipe"
Second Interim Report

REFERENCE: LP&L letter W3182-0036 dated September 20, 1982

Dear Mr. Collins:

At the present time, the required corrective action has not been completed.
Submittal of a final report will therefore be delayed until February 11, 1983.

Very truly yours,

L. V. Maurin
L. V. Maurin

LVM/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 3) E. Blake
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 4) W. Stevenson



8301250552 830113
PDR ADDCK 05000382
S PDR

IE 81



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

January 13, 1983

L. V. MAURIN
Vice President Nuclear Operations

W3I83-0007
Q-3-A35.07.62

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency Report No. 62
"Undersize Welds on 1/2" Schedule 160 Pipe"
Second Interim Report

REFERENCE: LP&L letter W3I82-0036 dated September 20, 1982

Dear Mr. Collins:

At the present time, the required corrective action has not been completed.
Submittal of a final report will therefore be delayed until February 11, 1983.

Very truly yours,

L. V. Maurin
L. V. Maurin

LVM/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 3) E. Blake
- 4) W. Stevenson

8301250552 830113
PDR ADOCK 05000382
S PDR

IE 27