

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

January 14, 1983

3 JAN 20 4 29

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Oconee Nuclear Station
Docket No. 50-287

Dear Mr. O'Reilly:

In Reportable Occurrence Report RO-287/82-12 dated December 1, 1982, a revised report containing the results of the laboratory analysis of the pulled tubes was estimated to be ready for submission by January 17, 1983. The destructive portion of the analysis will take considerably longer than the original estimate; thus, the report is not now ready. A revised report will be submitted as soon as the analysis is complete.

Very truly yours,



Hal B. Tucker

JFN/php

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector
Oconee Nuclear Station

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. E. L. Conner, Jr.
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

LE 20

8301260424 830114
PDR ADOCK 05000287
S PDR