



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 ■ CLEVELAND, OHIO 44101 ■ TELEPHONE (216) 622-9800 ■ ILLUMINATING BLDG ■ 55 PUBLIC SQUARE

Serving The Best Location in the Nation

Dalwyn R. Davidson

VICE PRESIDENT
SYSTEM ENGINEERING AND CONSTRUCTION

November 10, 1982

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Perry Nuclear Power Plant
Docket Nos. 50-440; 50-441
Response to I.E. Report
50-440/81-19; 50-441/81-19
Transmitted September 27, 1982

Dear Mr. Keppler:

Please refer to Page 8 of Attachment A to our letter dated October 27, 1982, responding to I.E. Report 50-440/81-19; 50-441/81-19. It has come to my attention that additional information is necessary to clarify our response to Noncompliance 440/81-09-03; 441/81-19-03. Paragraph 2(b) reads in part as follows:

"L. K. Comstock Nonconformance Report 1070 was generated to document the specific cable trays in question . . . to be acceptable."

This paragraph should read:

"L. K. Comstock NR 1070 was generated to document the condition of cable tray B1324. Other cable trays in question were documented on L. K. Comstock and Project Organization (Construction Quality Section) inspection reports and evaluated to be acceptable."

L. K. Comstock Procedure 4.3.3 was evaluated in order to determine its adequacy. No procedure revision was necessary.

8302040368 830128
PDR ADOCK 05000440
G PDR

NOV 15 1982

Mr. James G. Keppler


-2-

November 10, 1982

In addition, as a part of the evaluation, Nonconformance Reports written to document damage to cables were reviewed. None were related to sharp edges or burrs on cable trays. Based on the fact that no negative trend could be identified in this area, this condition is not considered to be generic, but represents an isolated case.

If there are additional questions please do not hesitate to call.

Sincerely,

A handwritten signature in cursive script, appearing to read "Dalwyn R. Davidson".

Dalwyn R. Davidson
Vice-President
System Engineering and Construction

DRD:llp

cc: Mr. M. L. Gildner
NRC Site Office

U. S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, D. C. 20555