

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 3 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 0 5
7 8 9 14 15 25 26 30 37 CAT 38

CON'T
0 1 REPORT SOURCE L 0 5 0 0 0 2 4 9 0 1 0 4 8 3 0 2 0 1 8 3 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While conducting routine surveillance DIS 700-3, SRM 24 high rod block was found to
0 3 exceed the Tech. Spec. limit of 1.00 E5 CPS. Safety significance was minimal because
0 4 other SRM channels would have produced a rod block if necessary. There was no effect
0 5 on public health or safety. Last previous occurrence of this type reported on R.O.
0 6 82-56/03L on Docket 050-237.

0 7
0 8

0 9 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE 0 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17
17 LER/RO REPORT NUMBER 8 3 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN E 18 FUTURE ACTION 2 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER G 0 8 0 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause is attributed to setpoint drift of the calibration potentiometer on the
1 1 217B module. I.M. inspected the module and found no abnormalities. SRM 24 was re-
1 2 adjusted immediately and tested successfully. DIS 700-3 will continue to be per-
1 3 formed weekly to verify operability.

1 4

1 5 FACILITY STATUS E 28 % POWER 0 9 8 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Test 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 ACTIVITY CONTENT RELEASED OF RELEASE 2 33 2 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER Ken Beverly

PHONE: 815-942-2920, X-521

8302080359 830201
PDR ADOCK 05000249
S PDR

NRC USE ONLY