

9104160201 910404  
PDR ADOCK 05000324  
PDP

DOCKET NO. 050-0325  
UNIT NAME Brunswick 1  
DATE March 1991  
COMPLETED BY Ronald Rumble  
TELEPHONE 919-457-2752

UNIT SHUTDOWNS AND POWER REDUCTIONS  
REPORT MONTH February 1991

NO.	DATE	TYPE 1	DURATION (HOURS)	REASON 2	METHOD OF SHUTTING DOWN REACTOR	LICENSEE EVENT REPORT NO.	SYSTEM CODE 4	COMPONENT CODE 5	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
91-003	910227	S	1.47	B	N/A	N/A	TA	N/A	Turbine Overspeed Trip Test

- 1: F - Forced  
S - Scheduled
- 2: Reason  
A - Equipment failure (explain)  
B - Maintenance or test  
C - Refueling  
D - Regulatory restriction  
E - Operator Training & License Examination  
F - Administrative  
G - Operational error (explain)  
H - Other (explain)
- 3: Method  
1 - Manual  
2 - Manual Scram  
3 - Automatic scram  
4 - Continuations  
5 - Load reductions  
6 - Other
- 4: EXHIBIT G - Instructions for preparation of data entry sheets for Licensee Event Report (LER) file (NUREG-0161)
- 5: EXHIBIT I - Same source