



PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4502

JOHN S. KEMPER
VICE-PRESIDENT
ENGINEERING AND RESEARCH

FEB 15 1983

Mr. Ronald C. Haynes, Director
United States Nuclear Regulatory Commission
Office of Inspection and Enforcement, Region I
631 Park Avenue
King of Prussia, PA 19406

Subject: Significant Deficiency Report No. 35
Final Report for HVAC Fabrication and
Installation Deficiencies
Limerick Generating Station, Units 1 and 2
NRC Construction Permit Nos. CPPR-106, -107

50-352, 50-353

Reference: a) Interim Report of March 23, 1981
b) Final Report of September 29, 1981

File: QUAL 2-10-2 (SDR #35)

Dear Mr. Haynes:

In our final report on the above subject deficiency, an error was made in paragraph 4.2. Paragraph 4.2 should read:

"Contractor has upgraded the quality surveillance of the subcontractor's fabrication shop to include 100% visual examination for Seismic I and IIA completed Duct Sections, Plenums, and shop fabricated hangers."

If there are any questions on this matter, we would be pleased to discuss them with you.

Sincerely,

LCD/mmk

Copy to: Director of Inspection and Enforcement
United States Nuclear Regulatory Commission
Washington, D. C. 20555
S. K. Chaudhary, Resident NRC Inspector