



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

February 17, 1983

L. V. MAURIN
Vice President Nuclear Operations

W3I83-0058
Q-3-A35.07.54

Mr. John T. Collins, Regional Administrator
Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 54
"Tube Steel (HT 16600) Laminations"
Fourth Interim Report

REFERENCE: LP&L letter W3K82-0271 dated May 11, 1982

Dear Mr. Collins:

At the present time, the corrective action as described in the reference above has not yet been completed.

A final report will therefore be submitted by March 18, 1983.

Very truly yours,

L. V. Maurin
L. V. Maurin

LVM/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) E. L. Blake

4) W. M. Stevenson

IE 27