

EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
0	9	I	B	D	Z	I	N	S	T	R	U	T	Z				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
LER/RO REPORT NUMBER		8	3	003		03		L		0							
21		22	23	24	25	26	27	28	29	30	31						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E	G	Z	Z	0	0	0	0	N	N	L	W	1	2	0			
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this incident was a deficiency in procedures. The procedures re-

1 1 quired a calibration check if 2 or more indications disagreed by more than 0.4

1 2 psig. This limit was not exceeded in this case, but still proved to be non-

1 3 conservative because all indications drifted in the same direction. Channels A,

1 4 B, and C were calibrated, and the procedure will be changed to require a calibra-

7 \* tion check whenever any one indication is more negative than -0.6 psig. 00

FACILITY STATUS (1) 5 (2) E (3) 28 (4) 1 (5) 0 (6) 0 (7) 29 (8) NA (9) 30  
 % POWER OTHER STATUS  
 METHOD OF DISCOVERY (10) A (11) 31 (12) Operator Observation (13) 32  
 ACTIVITY CONTENT RELEASED OF RELEASE (14) 1 (15) 6 (16) Z (17) 33 (18) Z (19) 34 (20) NA (21) 35  
 AMOUNT OF ACTIVITY (22) NA (23) 36  
 LOCATION OF RELEASE (24) NA (25) 36

PERSONNEL EXPOSURES									
NUMBER				TYPE		DESCRIPTION			
1	7	0	0	0	(37)	Z	(38)	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION		(41)	
1	8	0	0	0	(40)	NA	

LOSS OF OR DAMAGE TO FACILITY  
TYPE DESCRIPTION (43) NA

20		N		44		NA		NRC USE ONLY									
----	--	---	--	----	--	----	--	--------------	--	--	--	--	--	--	--	--	--

NAME OF PREPARER Jocelyn C. Petty

PHONE: (704) 373-8270