



Commonwealth Edison

One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

February 16, 1983

Mr. James G. Keppler, Regional Administrator
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Byron Station Units 1 and 2
Braidwood Station Units 1 and 2
Mechanical Snubber Bracket Interference
NRC Docket Nos. 50-454, 50-455, 50-456,
and 50-457

Reference (a): January 10, 1983 letter from T. R. Tramm to
J. G. Keppler.

Dear Mr. Keppler:

This is to provide a supplemental interim report on
resolution of a reportable deficiency involving mechanical snubber
bracket interference. Reference (a) provided the 30-day report of
this deficiency. It is numbered 82-09 for Byron Station and 82-09
for Braidwood Station.

In reference (a) we indicated that suspect snubber
assemblies will be inspected to determine the extent of necessary
repairs and the schedule for completion. At present the lists of
snubbers to be inspected have been compiled but the inspection
criteria have not yet been finalized.

Another report on this deficiency will be provided within
sixty days.

Please address questions regarding this matter to this
office.

Very truly yours,

T. R. Tramm
Nuclear Licensing Administrator

lm

8302280450 830216
PDR ADOCK 05000454
S PDR

6010N

FEB 23 1983

IE27