

VRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

Attachment to AECM-83/0122
Page 1 of 1

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LICENSEE CODE 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LICENSE NUMBER 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LICENSE TYPE 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAT 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE 74 75 76 77 78 79 80

REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

On January 28, 1983, the supervision system for fire doors OC220 and 1A211 indicated they were open (alarmed state), yet the doors were visually verified to be closed and the alarm would not reset. Fire detectors on one side of the doors were verified operable and an hourly fire watch was established in accordance with T.S.3.7.7 action a. This had no effect on the health and safety of the public and did not constitute a threat to plant safety. The event is reported pursuant to T.S.6.9.1.13.b.

0 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

SYSTEM CODE 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE CODE 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE SUBCODE 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

COMP. SUBCODE 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

VALVE SUBCODE 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LER/RO REPORT NUMBER 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

EVENT YEAR 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

SEQUENTIAL REPORT NO. 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

OCCURRENCE CODE 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

REPORT TYPE 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

REVISION NO. 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTION TAKEN 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FUTURE ACTION 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

EFFECT ON PLANT 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

SHUTDOWN METHOD 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

HOURS 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ATTACHMENT SUBMITTED 41 42 43 44 45 46 47 48 49 50

NPRD-4 FORM SUB. 42 43 44 45 46 47 48 49 50

PRIME COMP. SUPPLIER 43 44 45 46 47 48 49 50

COMPONENT MANUFACTURER 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 1 1 1 2 1 3 1 4 1 5 1 6 1 7 1 8 1 9 2 0 2 1 2 2 2 3 2 4 2 5 2 6 2 7 2 8 2 9 3 0 3 1 3 2 3 3 3 4 3 5 3 6 3 7 3 8 3 9 4 0 4 1 4 2 4 3 4 4 4 5 4 6 4 7 4 8 4 9 5 0

The cause of the alarm is indeterminable. Upon investigation, under maintenance work orders, no problems were found. Both doors and associated circuits were functionally tested, determined operable, and returned to service. This is a final report.

1 5 1 6 1 7 1 8 1 9 2 0 2 1 2 2 2 3 2 4 2 5 2 6 2 7 2 8 2 9 3 0 3 1 3 2 3 3 3 4 3 5 3 6 3 7 3 8 3 9 4 0 4 1 4 2 4 3 4 4 4 5 4 6 4 7 4 8 4 9 5 0

FACILITY STATUS 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

% POWER 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

OTHER STATUS 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

METHOD OF DISCOVERY 45 46 47 48 49 50

DISCOVERY DESCRIPTION 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

RELEASED OF RELEASE 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

AMOUNT OF ACTIVITY 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LOCATION OF RELEASE 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES NUMBER 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

TYPE 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

DESCRIPTION 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL INJURIES NUMBER 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

DESCRIPTION 41 42 43 44 45 46 47 48 49 50

LOSS OF OR DAMAGE TO FACILITY TYPE 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

DESCRIPTION 43 44 45 46 47 48 49 50

PUBLICITY 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ISSUED DESCRIPTION 45 46 47 48 49 50

2 0 1 2 1 3 1 4 1 5 1 6 1 7 1 8 1 9 2 0 2 1 2 2 2 3 2 4 2 5 2 6 2 7 2 8 2 9 3 0 3 1 3 2 3 3 3 4 3 5 3 6 3 7 3 8 3 9 4 0 4 1 4 2 4 3 4 4 4 5 4 6 4 7 4 8 4 9 5 0

8303010218 830224
PDR ADOCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER Matthew V. Rohrer and Boyd Shingleton PHONE