

USNRC REGION II  
ATLANTA, GEORGIA



83 FEB 25 410:34

February 22, 1983  
L-83-87

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2  
Docket No. 50-389, 10 CFR 50.55(e), 82-019  
Bent Small Bore Piping Not Inspected

On October 13, 1982, Florida Power and Light notified the NRC of a potential 10 CFR 50.55(e) condition existing at St. Lucie Unit No. 2 site involving inspection of approximately 240 small bore (2 inches and under) piping bends. Florida Power and Light has completed the piping inspection, but the results are still undergoing Engineering evaluation. Florida Power and Light will complete the Engineering evaluation and submit a final response by March 18, 1983.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/RJS/cab

8303010261 830222  
PDR ADOCK 05000389  
S PDR

OFFICIAL COPY

TE 27  
PEOPLE... SERVING PEOPLE