

APPROVED BY OMB
3150-0011
EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	5	4	V	C	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	0	0	0	4			5
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	LICENSE TYPE					30	CAT 55		

CON'T

7 8 01 REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

L 6 0 5 0 0 0 3 9 5 7 0 1 0 9 8 3 8 0 2 2 4 8 3 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On January 9, 1983, with the Plant in Mode 1, the Main Vent Exhaust System

0 3 | flow rate indication failed low. There were no adverse consequences in regards

0 4 | to this event. The flow rate indication was returned to operable status within

0 5 | two (2) hours and twenty (20) minutes of the event occurrence.

0 6 |

0 7 |

0 8 |

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE									
0	9	M	C	E		D		I	N	S	T	R	U	X		Z					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE				REPORT TYPE		REVISION NO.									
17		8	3			0	0	2			0	3	L		1						
25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42				
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
D		Z		Z		Z		0	0	0	0	Y		N		N		W	1	2	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause is attributed to corrosion on either the fuse block or card edge

1 1 connector of the Mixing Amplifier Circuit Board. The circuit board components

1 2 were cleared and indication returned to normal. The Licensee plans no

1 3 additional action.

1 4

FACILITY STATUS				% POWER				OTHER STATUS (30)				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION (32)							
1	5	B	(28)	0	5	0	(29)	N/A				A	(31)	Operator Observation									
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25					
ACTIVITY CONTENT RELEASED OF RELEASE								AMOUNT OF ACTIVITY (35)								LOCATION OF RELEASE (36)							
1	6	Z	(33)	Z	(34)	N/A				N/A													
2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20					

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	0	37	Z	38	N/A

PERSONNEL INJURIES
NUMBER DESCRIPTION (41)

1	2	3	4	5	6	7	8	9	10	11	12
1	8	0	0	0	0	0	0	0	0	0	N/A

8702010381 870202

1 2
LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)
1 9 Z (42) N/A S
7 8 9 10
8303010291 830222
PDR ADDCK 05000395
S PDR

ISSUED DESCRIPTION (45) N/A NRC USE ONLY

NAME OF PREPARER

C. J. McKinney

PHONE (803) 345-5209