

NRC FORM 366
(1-83)U.S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORTAPPROVED BY OMB
3150-0011
EXPIRES 4-30-82CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
0	1	s	c	v	c	s	l	1	2	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

CONT

01	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40			
0	1	R	E	P	O	R	T	S	O	U	R	C	E	6	0	5	0	0	0	3	9	5	7	0	1	1	2	8	3	8	0	2	2	2	8	3	9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On January 12, 1983, with the Plant in Mode 1, Fire Detector Zone DDD in

03 the Service Water Pumphouse failed to reset during the performance of

04 an operational test. There were no adverse consequences. An hourly fire

05 watch patrol established within one (1) hour of the occurrence provided

06 assurance that any fire would have been promptly discovered and extinguished.

07

08

09	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	
0	9	A	B	11	A	12	C	13	T	N	S	T	R	U	14	E	15	Z	16	17	8	3	1	0	0	5	0	3	L	1	1	2	8	3	9

17 LER/RO REPORT NUMBER

18 ACTION TAKEN

19 FUTURE ACTION

20 EFFECT ON PLANT

21 SHUTDOWN METHOD

22 HOURS

23 ATTACHMENT SUBMITTED

24 NFRD-4 FORM SUB.

25 PRIME COMP. SUPPLIER

26 COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The failure to reset was due to a grounded smoke detector. The detector

11 head had not been properly installed in the base of the assembly after a pre-

12 viously performed sensitivity test. The ground cleared after the head was

13 installed properly, and the system was returned to service on January 19, 1983.

14 Test personnel have been cautioned on the proper installation of smoke detectors.

15	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40		
1	5	B	28	0	5	0	29	N/A	30	B	31	Surveillance Test	32	33	2	34	N/A	35	N/A	36	37	2	38	N/A	39	40	41	42	43	44	45	46	47	48	49	50

16 ACTIVITY CONTENT RELEASED

17 PERSONNEL EXPOSURES NUMBER

18 PERSONNEL INJURIES NUMBER

19 LOSS OF OR DAMAGE TO FACILITY TYPE

20 PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER

C. J. McKinney

PHONE: (803) 345-5209