

BOSTON EDISON COMPANY

Certified By MalPROMPT REPORTABLE OCCURRENCETELECOPY MESSAGETO: (215) 337-5324  
Telephone NumberDATE/TIME: 2/17/83 11300TO: Ronald C. Haynes  
Regional Administrator, Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406FROM: Pilgrim Nuclear Power Station  
RFD#1, Rocky Hill Road  
Plymouth, MA 02360Docket Number 50-293  
License DPR-35Assigned LER Number 83-005/01X-0Reported per T.S. Section 6.9.B.1.d

Event Description: On 2/16/83, after discussions with G.E., it could not be verified  
that PNPS had operated within the T.S. required SDM of 0.25%  $\Delta$ k with rod 10-31 made  
inoperable, per T.S. 3.3.A.2, in the fully withdrawn position, for the period 2/6/83  
thru 2/11/83. During the event period, the rod was electrically disarmed, however,  
was fully capable of being scrammed. During a load reject scram on 2/12/83, the  
CRD did in fact scram within the required time.

Cause and Corrective Action: Determination of cause is under investigation.

Facility Status:

99 % Thermal MWc) Routine Startup \_\_\_\_\_  
d) Routine Shutdown \_\_\_\_\_  
e) Steady State X \_\_\_\_\_  
f) Load Changing \_\_\_\_\_g) Shutdown \_\_\_\_\_  
h) Refueling \_\_\_\_\_  
i) Other \_\_\_\_\_  
j) Not Applicable \_\_\_\_\_

A written followup report will be sent within two weeks.

NRC Person Notified J.R. Johnson  
Site Resident InspectorPrepared by G.G. Whitneycc: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Standard BECo. LER Distribution

8303010658 830217  
PDR ADOCK 05000293  
S PDR

IE29