


Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250, 50-251
IE Inspection Report 82-29 (Revised)

We have reviewed our initial response to IE Inspection Report 82-29 (L-82-469, dated October 29, 1982) and the comments of the resident inspector presented in IE Inspection Report 82-37. A revised report to the finding in Inspection Report 82-29 is attached.

Very truly yours,



Robert E. Uhrig
Vice President
Advanced Systems & Technology

(REU/PLP/mpc

Attachment

cc: Harold F. Reis, Esquire
PNS-LI-83-81

OFFICIAL COPY

8303010681 830222
PDR ADOCK 05000250
Q PDR

ATTACHMENT

RE: TURKEY POINT UNITS 3 AND 4
DOCKET NOS. 50-250, 50-251
IE INSPECTION REPORT 82-29

FINDING:

Technical Specification 6.8.1 requires, in part, that written procedures be implemented. Procedure A. P. 0103.4 specifies the method for placing and removing tags for administrative control of equipment.

Contrary to the above, steps 4.5, 8.5.2 and 8.6 of Administrative Procedure 0103.4, "In Plant Equipment Clearance Orders" were not fully implemented for equipment clearance order (ECO) 7-155 in effect from 7/19/82 to 7/23/82. A danger tag was improperly placed, the ECO form was not completed, and the clearance was not properly removed from valve MOV-878B in the safety injection system.

RESPONSE:

- (1-1) FPL concurs with the finding.
- (1-2) The reason for this finding was that the operator inadvertently did not specify on the clearance order that the breaker for MOV-4-878B should be tagged and the tag intended for the MOV switch on Vertical Panel B was inadvertently hung on the manual operator of the MOV instead.
- (1-3) As corrective action, the danger tag was removed from MOV-878B.
- (1-4) The operator was counseled on the need for proper completion of the equipment clearance order and compliance with plant procedures. The Administrative Procedure 0103.4, In-Plant Clearance Orders, has been revised to better describe where clearances are placed and to change the provisions for temporary clearance releases.
- (1-5) Full compliance was achieved on September 30, 1982.