


Southern California Edison Company



P. O. BOX 800

2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

J. G. HAYNES

MANAGER OF NUCLEAR OPERATIONS

March 3, 1983

TELEPHONE
(213) 572-1742

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Administrator

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station
Units 2 and 3

As requested in IE Bulletin No. 82-04: Deficiencies in Primary Containment Electrical Penetration Assemblies, this letter provides our response to Action Item No. 5 for San Onofre Units 2 and 3. A review has been conducted, and we have determined that no Bunker Ramo containment electrical penetration which uses the hard epoxy module design is installed or is planned to be installed in safety related systems at San Onofre Nuclear Generating Station, Units 2 and 3.

Subscribed on this 3rd day of March, 1983.

Very truly yours,

By

J. G. Haynes
J. G. Haynes

Manager of Nuclear Operations

Subscribed and sworn to before me
this 3rd day of March, 1983



Dona Mary Wilcomb
Notary Public in and for the County
of Los Angeles, State of California

Enclosure

cc: Director, Office of Inspection
and Enforcement, NRC
A. E. Chaffee, USNRC
Site Inspector, S023

8303070055 830303
PDR AD0CK 05000361
Q PDR

IE11