



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2931 • BEAUMONT, TEXAS 77704


AREA CODE 713 638-6631

February 28, 1983

RBG- 14,481

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-72

On August 30, 1982, Gulf States Utilities Company (GSU) notified the Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning the improper installation (torquing), testing, and inspection of concrete drilled-in-expansion-type anchors (DR-72). GSU's evaluation has not been completed. GSU is awaiting additional information from our architect-engineer, Stone & Webster. An interim or final status report will be provided by April 25, 1983.

Sincerely,

for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

IE 27

8303110219 830228
PDR ADOCK 05000458
S PDR