

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY  
STATION MANAGER

February 25, 1983

RECEIVED  
NRC  
SCE  
1983 MAR -1 PM 12:14  
REGION V  
TELEPHONE  
(714) 492-7700

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator


Dear Sir:

Subject: Docket No. 50-361  
30-Day Report  
Licensee Event Report No. 83-011  
San Onofre Nuclear Generating Station, Unit 2

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-10 for San Onofre Unit 2, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.3.1 associated with the Reactor Protection System (RPS). Enclosed LER 83-011 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding this event, please contact me.

Sincerely,



Attachment

cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Units 2 & 3)  
R. J. Pate (USNRC Resident Inspector, San Onofre Units 2 & 3)

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission  
Office of Management Information and Program Control

Institute of Nuclear Power Operations

8303110225 830225  
PDR ADDCK 05000361  
S PDR

IE-22  
83-90