

CONTROL BLOCK:

0	1	T	N	S	N	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			S		
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	37	CAT. NO.		

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 0 2 0 5 8 3 8 0 3 0 3 8 3 9
60 61 68 69 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Unit 1 was in mode 1 p' 7% with the RCS temperature and pressure at 579 degrees F

03 | and 2240 psig. During the performance of surveillance instruction (SI) 16, it was

04 [] discovered that channel 119P and 1113 of the boron injection tank (BIT) piping was

05 | inoperable. This required entry into LCO 3.5.4.2. There was no effect upon public

06 health and safety. Previous occurrences - one (SQRO-50-327/82072).

0	7
---	---

0	8
---	---

0	9
---	---

SYSTEM CODE S F 9 10 11		CAUSE CODE E 12		CAUSE SUBCODE A 13		COMPONENT CODE I N S T R U 14 15		COMP. SUBCODE C 16		VALVE SUBCODE Z 17	
17 LER/RO REPORT NUMBER EVENT YEAR 8 3 21 22		23		24 SEQUENTIAL REPORT NO. 0 2 1 26		27 OCCURRENCE CODE / 28		29 REPORT TYPE 0 3 30		31 REVISION NO. / 32	
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23	
33		34		35		36		37		38	
39		40		41		42		43		44	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Channel 119P and 111S were found to be inoperable because of failed Thermon Manu-

facturing Controller Model No. 48-816-8133. For channel 119P, a 10 ampere Littlefuse

1 2 was blown, and for channel 111S, Sigma Instruments relay Model No. 50R02-23152 was

bad. These failures are random and can be attributed to normal wear. The fuse and

relay were replaced and the channels returned to service.

100

FACILITY STATUS (1) 5 (2) E (28) 1 0 0 (29) NA (30) OTHER STATUS
 METHOD OF DISCOVERY (31) B (32) Surveillance test (33) DISCOVERY DESCRIPTION
 ACTIVITY CONTENT (34) Z (35) Z (36) NA (37) AMOUNT OF ACTIVITY
 RELEASED OF RELEASE (38) NA (39) LOCATION OF RELEASE
 PERSONNEL EXPOSURES (40) 0 0 0 (41) Z (42) NA (43) DESCRIPTION
 NUMBER TYPE
 PERSONNEL INJURIES (44) 0 0 0 (45) NA (46) DESCRIPTION
 NUMBER DESCRIPTION
 LOSS OF OR DAMAGE TO FACILITY (47) Z (48) NA (49) DESCRIPTION
 TYPE DESCRIPTION
 PUBLICITY (50) N (51) NA (52) DESCRIPTION
 ISSUED DESCRIPTION
 8303140554 830303
 PDR ADOCK 05000327
 S PDR
 NRC USE ONLY

Name of Preparer: W. C. Ludwig /M. R. Harding

Phone: (615) 751-0349