



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

February 28, 1983

Mr. R.C. Haynes
Director, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 83-021/01P-0
ER 100450 FILE 841-23
PLA- 1553

Docket No. 50-387
License No. NPF-14

Dear Mr. Haynes:

This transmission confirms the telephone report of February 25, 1983, by F.T. Eisenhuth to A.T. Gody of your staff, concerning failure to comply with License Condition 2.c(5).

As indicated in that report, non-qualified containment vent and purge valves in lines greater than 2 inches, were not maintained "lock-closed" when the plant entered an applicable mode for primary containment integrity requirements. However, the valves were in actuality closed throughout the incident, and measures to restore electrical isolation to provide "lock-closed" protection were instituted immediately upon discovery.

This condition is considered reportable in accordance with License Condition 2.G.

H.W. Keiser
Superintendent of Plant-Susquehanna

LAK/cg

cc: Director, Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director, Office of Management & Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555