



RICHARD P. CROUSE
Vice President
Nuclear
(419) 258-5221

Docket No. 50-346

License No. NPF-3

Serial No. 1-332

March 7, 1983

Mr. James G. Keppler, Director
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Ill. 60137

Dear Mr. Keppler:

This is in response to IE Bulletin 83-01 dated February 25, 1983 (Log No. 1-740) concerning Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal. In accordance with the Bulletin, Toledo Edison has determined that the breakers using undervoltage trip attachment in the Reactor Protection System are not the Westinghouse DB-50 type. Therefore, no further action is required for IE Bulletin 83-01 for Davis-Besse Nuclear Power Station Unit No. 1.

Very truly yours,

RPC:GAB:lah

cc: DB-1 NRC Resident Inspector

8303150274 830307
PDR ADOCK 05000346
Q PDR

IEW

ATOMIC ENERGY ACT OF 1954
SECTION 182a
SUBMITTAL IN RESPONSE
FOR THE
DAVIS-BESSE NUCLEAR POWER STATION
UNIT NO. 1
FACILITY OPERATING LICENSE NPF-3

This letter is submitted in conformance with Atomic Energy Act of 1954 Section 182a in response to IE Bulletin 83-01 (Log No. 1-740). This deals with Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal.

By *[Signature]*
Vice President, Nuclear

Sworn to and subscribed before me this 7th day of March, 1983.

Laurie A. Brudzinski
Notary Public (*Brudzinski*)
LAURIE A. BRUDZINSKI
Notary Public, State of Ohio
My Commission Expires May 16, 1986