

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

REPORT
SOURCE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

previous occurrence reported by R.O 83-06 on Docket #50-249.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

and the valve was successfully operated from the control room.

PHONE: 815-942-2920, X526