



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

March 2, 1983

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

83 MAR 7 410:58

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-335.0
Update Report - Fire Seal Not
Installed
LER 82-032/99 X-1
AECM-83/0144

This letter submits an update to a previous report submitted on August 26, 1982. The event for which the report was submitted occurred on July 23, 1982, when it was observed that a fire rated seal was not installed in an electrical penetration between the Hot Machine Shop and the Division 2 ESF Switchgear Room. The event was reported pursuant to Technical Specification 3.7.7.a and 6.9.2.

The penetration has since been sealed and all corrective action is complete. Attached is LER 82-032/99 X-1, which is a final report.

Yours truly,

FOR J. P. McGaughy, Jr.

JPM:sap
Attachment

cc: Mr. N. L. Stampley (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

IF 22

Member Middle South Utilities System

8303140388 830302
PDR ADOCK 05000416
PDR
S