



Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038

Nuclear Department

March 1, 1983

Mr. Ronald C. Haynes, Regional Administrator  
Region I - Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Dear Mr. Haynes:

IE BULLETIN 82-04  
DEFICIENCIES IN PRIMARY CONTAINMENT  
ELECTRICAL PENETRATION ASSEMBLIES  
SALEM GENERATING STATION  
UNITS NO. 1 AND 2  
DOCKET NOS. 50-272 AND 50-311

The following is Public Service Electric and Gas Company's  
reply to the subject Bulletin, in accordance with Action Item  
5.a:

Bunker Ramo electrical penetrations are not used on Salem  
Units 1 and 2. In addition, there are no plans to install  
Bunker Ramo penetrations at Salem Generating Station.  
Therefore, no further action is needed.

If you have any further questions in this regard, please do  
not hesitate to contact us.

Very truly yours,

E. A. Biden  
Manager - Nuclear  
Licensing and Regulation

CC: Mr. Donald C. Fisher  
Licensing Project Manager

Mr. Leif Norrholm  
Senior Resident Inspector

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

IE24