



Docket No. 50-346

License No. NPF-3

Serial No. 919

March 11, 1983

RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221

Mr. Darrell G. Eisenhut, Director
Division of Licensing
Office of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Eisenhut:

In the Commission Order dated December 10, 1982 (Log No. 1157) a 90-day response was required to provide design information and implementation schedules on Inadequate Core Cooling instrumentation. Toledo Edison made arrangements to provide the necessary information for the Davis-Besse Nuclear Power Station Unit No. 1 by the required due date but find that due to an administrative error, we are unable to meet the March 10, 1983 due date. We have verbally notified our Project Manager of this fact and will provide the required response by March 22, 1983.

Very truly yours,

RPC:LDY:lah

cc: DB-1 NRC Resident Inspector

A001

8303150499 830311
PDR ADOCK 05000346
PDR