



**GPU Nuclear Corporation**  
Post Office Box 388  
Route 9 South  
Forked River, New Jersey 08731-0388  
609 971-4000  
Writer's Direct Dial Number:

C321-94-2109  
July 7, 1994

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555


Dear Sir:

Subject: Oyster Creek Nuclear Generating Station  
Docket No. 50-219  
Reply to a Notice of Violation  
Inspection Report 94-10

In accordance with 10 CFR 2.201, Attachment 1 provides GPUN's response to the violation identified in the subject inspection report.

If you should have any questions or require further information, please contact Brenda DeMerchant, DC Licensing Engineer at (609) 971-4642.

Very truly yours,



John J. Barton  
Vice President & Director  
Oyster Creek

JJB/BDEM:jc  
cc: Administrator, Region 1  
Senior NRC Resident Inspector  
Oyster Creek NRC Project Manager

110007  
9407110177 940707  
PDR ADDCK 05000219  
Q PDR

GPU Nuclear Corporation is a subsidiary of General Public Utilities Corporation

TEO1

**Violation:**

Technical Specification 6.8.1 requires that written procedures shall be established, implemented and maintained that meet or exceed the requirements of Regulatory Guide (RG) 1.33, including administrative procedures.

Station Procedure No. 119.5, "Loose Equipment Storage," provides the requirements for anchoring and storing loose equipment in the Reactor Building (RB) and Turbine Building (TB).

Contrary to the above, during the inspection period for April 19, 1994, through May 30, 1994, multiple examples of improperly anchored and stored loose equipment were identified both in the RB and TB.

This is a Severity Level IV violation (Supplement 1).

**Response:**

GPUN concurs with the violation as stated.

The cause for this violation was a programmatic weakness in the implementation of the Oyster Creek 119.5 procedure for loose equipment control.

Corrective actions were immediately initiated by sending out teams to secure or restrain all identified instances of improperly anchored and stored loose equipment.

**CORRECTIVE STEPS THAT WILL BE TAKEN TO AVOID FURTHER VIOLATIONS:**

The Maintenance Director will issue a memo to the entire Maintenance staff outlining Oyster Creek's failure to comply with the requirements of OC Station Procedure No. 119.5, "Loose Equipment Storage" thus constituting a violation of technical specification requirements. Additionally, all Maintenance personnel will be sensitized as to their accountability and responsibility to comply with the subject procedure. Other applicable departments on site will issue a similar memo to their staffs.

The above memo will be reviewed at all Maintenance crew meetings so that the message is transmitted down to the work force.

The members of the Management Observation team and the Off-Shift Tour Program will be re-sensitized as to the requirements of Procedure 119.5.

**DATE FOR FULL COMPLIANCE:**

August 31, 1994 when the above noted corrective actions are completed.