

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE							14	LICENSE NUMBER											25	LICENSE TYPE					30	57 CAT 58		

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	0	0	0	0	3	1	5	7	1	2	3	0	8	2	8	0	5	1	6	8	3	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 WHILE PERFORMING AN ICE CONDENSER TOUR, AN OPERATOR DISCOVERED ONE INTERMEDIATE

03 DECK DOOR FROZEN SHUT. THIS IS NON-CONSERVATIVE WITH RESPECT TO T.S. 3.6.5.3.

04 THE ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

05 THE REMAINING 191 DOORS REMAINED CLOSED AND OPERABLE. PREVIOUS OCCURRENCES WERE

06 1315/76-10, 80-021, 80-024; 316/81-029 and 81-038.

07 _____

08 _____

SYSTEM CODE 9 10		CAUSE CODE 11 12		CAUSE SUBCODE 12 13 14 15 16 17					COMP. SUBCODE 18 19		VALVE SUBCODE 20 21	
S 11		X 12		X X X X X 14					Z 15		Z 16	
0 9												
7 8												
LER/RO REPORT NUMBER 21 22		EVENT YEAR 23 24		SEQUENTIAL REPORT NO. 25 26		OCCURRENCE CODE 27 28		REPORT TYPE 29 30		REVISION NO. 31 32		
17		8 2		1 1 0		/		D 3		1		
ACTION TAKEN 33 34		FUTURE ACTION 35 36		EFFECT ON PLANT 37 38		SHUTDOWN METHOD 39 40		HOURS 41 42		ATTACHMENT SUBMITTED 43 44		
X 18		Z 19		Z 20		Z 21		0 0 0 0 22		N 23		
33 34		35 36		37 38		39 40		41 42		43 44		
NPRD-4 FORM SUB. 45 46		PRIME COMP. SUPPLIER 47 48		COMPONENT MANUFACTURER 49 50								
N 24		N 25		W 1 2 0 26								
45 46		47 48		49 50								

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE ICE WAS REMOVED AND THE DOOR WAS OPERABLE WITHIN 2 HOURS. CAREFUL EXAMINATION

11 COULD NOT DETERMINE THE SOURCE OF MOISTURE. SUBSEQUENT DOOR CHECKS HAVE SHOWN NO

1 2 | FURTHER PROBLEMS WITH ANY DOORS. THIS REVISION TRANSMITTED DUE TO ADDITION OF

1	3	PREVIOUS OCCURRENCES AND CAUSE SUBCODE CHANGE.
---	---	--

1 4

8 9 FACILITY STATUS (28) 1 5 E 10 11 12 % POWER 1 0 0 13 14 15 OTHER STATUS (30) NA 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 METHOD OF DISCOVERY (31) B 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 33 7 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA				

		PERSONNEL INJURIES						
		NUMBER			DESCRIPTION			(41)
1	2	3	4	5	6	7	8	90
1	2	0	0	0	0	NA		80

8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE DESCRIPTION

1 9 Z (42) NA

7 8 9 10

8305240370 830516
PDR ADOCK 05000315
S PDR

80

ISSUED DESCRIPTION (45) NA NRC USE ONLY

NAME OF PREPARER M. J. CAMP

PHONE (616) 465-5901