

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

82 FEB 19 P 2: 11

February 17, 1982

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-328/82011

The enclosed report provides details concerning a failure to include  
unit 2 boron injection tank in Surveillance Instruction SI-16. This  
report is submitted in accordance with Sequoyah unit 2 Technical  
Specification 6.9.1.13.c.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Green*

J. J. Green  
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Records Center  
Institute of Nuclear Power Operations  
1820 Water Place  
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

8203080414 820217  
PDR ADOCK 05000328  
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

IE 22 511