

Georgia Power Company
Post Office Box 442
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444

UNNRC REGION II
ATLANTA, GEORGIA

Edwin I. Hatch Nuclear Plant



Georgia Power

the southern electric system

02 FEB 25 P 1: 52

February 16, 1982
PM-82-111




PLANT E. I. HATCH
Special Report
Docket No. 50-366

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Pursuant to Section 6.9.2 and 3.5.1 action: c. of Hatch Unit 2 Technical Specifications, please find attached Special Report.


M. Manry
Plant Manager

MM/SXB/bje

xc: G. F. Head
J. T. Beckham, Jr.
T. V. Greene
C. T. Jones
S. X. Baxley
Control Room
File M-58
Document Control

OFFICIAL COPY

IR 22

5/11

8203080540 820216
PDR ADOCK 05000366
S PDR

Special Report
Georgia Power Company
Plant E. I. Hatch
Docket No. 50-366

HPCI INJECTION INTO REACTOR

On 1-23-82 at 20:41, reactor feed pump (RFP) "B" tripped while performing the weekly RFP surveillance test. RFP "A" was isolated for maintenance. Reactor vessel level decreased causing a reactor scram and isolation. HPCI auto. initiated and injected into the reactor to restore and maintain level.

As of the date of this report, there have been twenty-two (22) incidents with HPCI injections into the reactor vessel.