

Washington Public Power Supply System

Box 1223 Elma, Washington 98541 (206) 482-4428

Docket Numbers 50-508 and 50-509

April 21, 1982
G03-82-412



Document Control Desk
U. S. Nuclear Regulatory Commission
Washington D. C. 20555

Subject: PROJECT NOS. 3 AND 5
10CFR50.55(e) REPORTABLE CONDITION
WELDING DEFICIENCIES IN RP PLATES (D/N #25)

Attached is a copy of the final report provided to Region V concerning a 10CFR50.55(e) deficiency associated with the subject condition.

Should you have any questions or desire further information, please contact me directly.

A handwritten signature in cursive script, appearing to read "R. S. Leddick".

R. S. Leddick, 760
Program Director, WNP-3

DRC/tt

Attachment

cc: J. Adams - NESCO-WO/A
D. Smithpeter - BPA-WO/A
Ebasco - New York-WO/A
WNP-3/5 Files - Richland-WO/A

IF27
5/11

8204270127
S