



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345


April 20, 1982

G. D. McLendon  
Senior Vice President

W3K-82-0241

Q-3-A35,07

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Final Report of Potentially Reportable Deficiency No. 60  
"B-Line Fittings Defects"

References: (1) Telecon - L. L. Bass (LP&L) to B. Crossman (USNRC) on 3/2/82  
(2) LP&L Letter W3K-82-0137 to USNRC dated 3/5/82

Dear Mr. Collins:

We have completed our evaluation of the reportability of the subject deficiency under 10CFR50.55(e) and have determined that it is not reportable. The results of our review are on file at the Waterford SES Unit 3 site and are available for your inspection.

Very truly yours,

*G. D. McLendon*

GDMcL/LLB/grf

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

IE-27  
5/10

8204270247

5

