

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT
SOURCE

0 1
7 8

REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 0 3 2 6 8 2 8 0 4 1 3 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | A gaseous release from the Waste Gas System was initiated at 2250 hours,

03 | March 26, 1982. The Control Room Operator failed to align the Containment/Plant _____

0	4	Vent Monitors 1R11A, 1R12A and 1R12B to the plant vent as required by Operating
---	---	---

05 | Instruction O.I.II-12.3.3.

0	6	
---	---	--

07 _____

08 _____

0 9		SYSTEM CODE M B		CAUSE CODE A		CAUSE SUBCODE A		COMPONENT CODE I N S T R U						COMP. SUBCODE E		VALVE SUBCODE Z														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23														
LER/RO REPORT NUMBER		EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 1 6		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN H		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER T 3 0 0		
17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The failure of the operator to properly perform the operating instruction resulted
---	---	--

1 | 1 | in the incorrect vent monitor alignment. LCO 2.3.4.c was met at 0048 hours.

1 2 | March 27, 1982, with the termination of the gaseous release. ETS release rate limits

1 3 | were not exceeded, and there was no adverse impact on the environment. The operator

1 4 involved was counseled by the Senior Shift Supervisor concerning LCO 2.3.4.c and

FACILITY	COUNTRY	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
		(30)		(32)

STATUS		POWER			OTHER STATUS		DISCOVERY		DISCOVERY TIME		
1	5	G	(28)	0	0	0	(29)	N/A	A	(31)	Operator Observation

7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT

25 26

RELEASED OF RELEASE				AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	6	2	33	N/A	N/A

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION
1	2	3	4	5

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

PERSONNEL INJURED	
NUMBER	DESCRIPTION (41)
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

7	8	9	10	11	12	N/A										80
---	---	---	----	----	----	-----	--	--	--	--	--	--	--	--	--	----

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	

[illegible]

PUBLICITY ISSUED — DESCRIPTION (45) NRC USE ONLY

NRC USE ONLY

2	0	N	(44)	N/A										68	69	80
---	---	---	------	-----	--	--	--	--	--	--	--	--	--	----	----	----

NAME OF PREPARER

R. Frahm

PHONE: 609-935-0998

8204270859