

(CAR 1361)

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	R	E	G	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE							14	LICENSE NUMBER											25	LICENSE TYPE					30	CAT		58

CON'T

0	1	REPORT SOURCE										L	6	0	5	0	-	0	2	4	4	7	0	3	2	0	8	2	8	0	4	1	6	8	2	9												
7	8											60	61	DOCKET NUMBER										68	69	EVENT DATE										74	75	REPORT DATE										80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Due to installation of a new Undervoltage System on Safeguard Buses 16 & 17 per

0 3 EWR-1444, Bus 17 was out of service for more than 7 days. This bus supplies

0 4 power to the Motor Driven Fire Pump. So therefore based on Tech Spec 3.14.2.1b,

0 5 the Motor Driven Fire Pump was inoperable more than 7 days and a 30 day written

0 6 report is required.

0 7

0 8

7 8 9 80

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
0	9	A	B	B	X	P	U	M	P	X	X	B	Z				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17		8	2		0	0	9		0	3	L						
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
X	X	Z	Z						0	0	0	N	N	A		P	1
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Buses 16 & 17 were taken out of service on 03/13/82 in order to install the new

1 1 Undervoltage System per EWR-1444. Due to installation and testing problems,

1 2 the duration of this bus-outage was more than 7 days. On 03/26/82, Buses 16 & 17

1 3 were returned to service and the Motor Driven Fire Pump was returned to

1 4 operable status.

7 8 9 80

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) H

% POWER (29) 0 0 0 NA

OTHER STATUS (30)

METHOD OF DISCOVERY (31) Z NA

DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

NA

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	000	NA

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
00040	NA

1		9		Z		42		NA		43	
1		9		Z		42		NA		43	

7 8 9 10 80

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) NA

NRC USE ONLY

NRC USE ONLY

8204270490

Ed Webb/J. C. Bodine

PHONE: 315-524-4446 Ext. 381/255

0260 917-926