



**Florida
Power**
CORPORATION

April 25, 1983
3F-0483-18

Mr. J. P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
101 Marietta Street N.W., Suite 2900
Atlanta, GA 30303

SUBJECT: Crystal River Unit 3
Docket No. 50-302
Operating License No. DPR-72
IE Inspection Report No. 83-04

Dear Mr. O'Reilly:

Florida Power Corporation's response to Inspection Report 83-04, due April 22, 1983, will be submitted April 29, 1983. A procedural deficiency has been identified concerning abnormal and emergency procedure review. Additional reviews are being performed to determine if the abnormal and emergency procedural review is being accomplished and documented through other means.

Sincerely,

G. R. Westafer
Manager
Nuclear Licensing and Fuel Management

PGH/mm

Enclosure

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8305270312 830520
PDR ADDCK 05000302
PDR
Q