

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	A	S	O	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE						30	57 CAT		58

CON'T

REPORT SOURCE: 01 60 61 05 00 36 17 68 69 06 09 82 74 85 75 07 23 82 80 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | The turbine overspeed protection system was rendered inoperable in order to locate  
0 3 | and repair oil leaks in the L. P. Turbine Intercept Valve Actuator. LCO 3.3.4  
0 4 | Action b requires that the turbine be isolated from the steam supply within 6 hours.  
0 5 | Isolation was immediately achieved because the MSIV's and Turbine Stop Valves  
0 6 | were closed. There was no effect on public health and safety as the closed  
0 7 | MSIV's and Turbine Stop Valves provided redundant protection.  
0 8 |  
7 8 9

SYSTEM CODE 0 9		CAUSE CODE H A		CAUSE SUBCODE E		COMPONENT CODE V A L V O P				COMP. SUBCODE X		VALVE SUBCODE Z					
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER 8 2		EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 3 3		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0							
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN B		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER X 9 9 9	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Repairs to oil leak on unitized actuator. The immediate corrective action was

in place as the MSIV's turbine stop valves were closed. No additional corrective

actions are needed.

FACILITY STATUS		% POWER			OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
1	5	B	28	0 0 0	29 NA	B 31	Operator Observation

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 Z 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES											
NUMBER			TYPE	DESCRIPTION							
1	7	0	0	0	37	38	NA				39

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		1																																																																																															

8 9 10 80  
PUBLICITY  
ISSUED DESCRIPTION (45) 8208020417 820722  
PDR ADOCK 05000361  
S PDR NRC USE ONLY  
2 0 N (44)

NAME OF PREPARER

H. B. Ray

DELINQ

714/492-7700