

Southern California Edison Company

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER
VICE PRESIDENT
NUCLEAR GENERATION

July 29, 1994

TELEPHONE
714-368-6255

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket Nos. 50-361 and 50-362
Licensee Event Report No. 94-003
San Onofre Nuclear Generating Station, Units 2 and 3


Reference: Letter from Edison (R. W. Krieger) to NRC Document
Control Desk dated May 20, 1994; Subject: Licensee
Event Report 94-003

In accordance with the requirements of 10 CFR 50.73(d), by the referenced letter, Edison provided a Licensee Event Report for several missed fire protection Technical Specification surveillances. When the LER was submitted, Edison had not completed our evaluation of the cause(s) of the missed surveillances and the LER indicated that Edison planned to submit a revision by July 29, 1994 to report the results of our evaluation.

While conducting our evaluation, Edison determined the initial cause of the missed surveillances to be procedure revision errors. However, based on several other recent errors involving the conduct of surveillances, Edison management believes it prudent to collectively examine these other errors. Consequently, Edison will continue our evaluation and when complete, will submit a revision to LER 94-003 to report our findings.

If you require any additional information, please so advise.

Sincerely,



cc: L. J. Callan, Regional Administrator, NRC Region IV
K. E. Perkins, Jr., Director, Walnut Creek Field Office, NRC
Region IV
J. A. Sloan, NRC Senior Resident Inspector, San Onofre Units
2 & 3
M. B. Fields, NRC Project Manager, San Onofre Units 2 and 3
Institute of Nuclear Power Operations (INPO)

9408030184 940729
PDR ADDCK 03000361
S PDR

IE22
1/0