

Attachment to AECM-83/0291

PE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)7 812

PHONE

NRC USE ONLY

017-938



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

May 18, 1983

JAMES P. McGAUGHY, JR.
VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - Duct Covers
Not Installed
LER 82-138/99 X-1
AECM-83/0291

This is an update to a previous report submitted on December 16, 1982. The event for which the report was submitted occurred on November 12, 1982, when several duct covers were not installed because cables extending through the ducts would not allow their installation. An Limiting Condition for Operation was entered in accordance with Technical Specification 3.7.7. A Special Report was submitted pursuant to Technical Specification 6.9.2.

An engineering evaluation has determined that some barriers should be modified and others do not require modifications. Barriers requiring modification are expected to be restored by June 30, 1983. Attached is LER 82-138/99 X-1.

Yours truly,

L. P. Doherty
for J. P. McGaughy

JPM:sap
Attachment

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

TE 22
11

83 MAY 24 A10:53

REGION I
ATLANTA, GEORGIA