



Commonwealth Edison

One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

September 2, 1982

Mr. James G. Keppler, Regional Administrator
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Byron Station Units 1 and 2
I&E Inspection Report Nos.
50-454/82-05 and 50-455/82-04

Dear Mr. Keppler:

This is to provide a revised schedule for completion of certain training which is part of the corrective action being taken to correct a Byron Station construction deficiency discussed in I&E Inspection Report numbers 50-454/82-05 and 50-455/82-04.

Our response to item 2 of the Notice of Violation attached to reference (a) indicated that procedure revisions emanating from the review of contractor procedures would be implemented by September 1, 1982. As of that date 154 of 167 people have been trained on the revised procedures. Training of the remaining few will be completed by September 30, 1982.

Please address questions regarding this matter to this office.

Very truly yours,

T. R. Tramm
Nuclear Licensing Administrator

lm

4944N