

CP&L

Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

October 1, 1982

FILE: B09-13510C
SERIAL: BSEP/82-2145

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1
DOCKET NO. 50-325
LICENSE NO. DPR-71

CONFIRMATION FACSIMILE OF AN IMMEDIATELY REPORTABLE EVENT (1-82-100)


Dear Mr. O'Reilly:

This confirms the telephone conversation at 0930 on October 1, 1982, between Mr. R. M. Poulk, Jr., and Mr. C. W. Hehl, concerning an immediately reportable event per Technical Specification 6.9.1.8i.

Carolina Power and Light Company was notified by United Engineers and Constructors that analysis indicates that pipe support PS-6647, located on the tailpipe for SRV F013H where it passes through the deflector plate, could possibly fail during a seismic event.

Since the support is simple in design and could be upgraded to meet all requirements at a minimum expense, it was corrected as an STF rather than incur the expense to perform additional analysis to remove conservatism which may have proved it to be an LTF. The corresponding support on Unit No. 2 meets code requirements.

Very truly yours,



C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/gvc/LETGC3

Enclosure

cc: Mr. R. C. DeYoung

8210080220 821001
PDR ADOCK 05000325
S PDR

OFFICIAL COPY

10-22

82 OCT 5 AM 10:30

USNRC REGION II
ATLANTA, GEORGIA