


LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

May 30, 1983

W3I83-0195
Q-3-A35.07.68

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 68
"Spurious ESFAS Actuation"
Third Interim Report

REFERENCE: LP&L letter W3P83-1015 dated March 31, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than May 31, 1983.

At the present time, all corrective action has been completed. The supporting documentation is being assembled for Quality Assurance review. This review is expected to be completed one (1) week after receipt by Quality Assurance.

Therefore, a Final Report will be submitted to the NRC by June 24, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8306070133 830530
PDR ADDCK 05000382
S PDR

IE-27

1/0